


Range (Display range)	Resolution (Accuracy guarantee range)	Measurement accuracy
999.9 Hz (40.0 Hz to 999.9 Hz)	0.1 Hz (40.0 Hz to 999.9 Hz)	±1.5% rdg ±0.1 Hz



## Names and Function of Parts



### Operation keys

Key	Press once	Press for 1 sec. or more
 AUTO HOLD	Retains measured value ( <b>HOLD</b> lights up) (Cancel: Press the <b>HOLD</b> key), saves measured value when using the GENNECT Cross.	Turns the auto hold function on or off. ( <b>HOLD</b> flashes)
 COMP	Turns the display backlight on and off. Automatically deactivates the backlight when the instrument is not in use for 40 sec.	Turns the comparator function on or off. ( <b>COMP</b> lights up)
 FILTER	Switches among the maximum value, minimum value, average value, maximum peak value, minimum peak value, and current value. <b>MAX</b> ▶ <b>MIN</b> ▶ <b>AVG</b> ▶ <b>PEAK MAX</b> ▶ <b>PEAK MIN</b> ▶ _____ Cancel: Press the <b>MAX/MIN</b> key for 1 sec. or more.	Turns the filter function on or off. ( <b>FILTER</b> lights up)
 ~A/Hz	Switches among the auto range, 60.00 mA range, 600.0 mA range, 6.000 A range, 60.00 A range, and 600.0 A range.	Switches frequency measurement and current measurement.

### Power-on Option

(Turns the power on while pressing operation keys)

Key	Function	Default value	Setting retained?
+	Cancels the auto power save function (APS) off.	On	No
+	Automatic backlight deactivation (on or off)	On	Yes
+	Turns the filter function on or off when the instrument is powered on.	Off	Yes
+	Beep (on or off)	On	Yes
+  +	Displays Serial No.	—	—
+  +	Displays model number, version of software, and all indicators.	—	—

## Making Measurements

To ensure that the instrument is properly operating, conduct an inspection and check instrument operation before using instrument to ensure that no damage has occurred during storage or transport. Verify that the tips of the jaws are free of damage and cracking. If there is any damage to the instrument, contact your authorized Hioki distributor or reseller for repair.




**DANGER**

- To prevent an electric shock, do not touch any areas beyond the barrier while the instrument is in use.
- The maximum measurement current varies with the frequency, and the current that can be measured continuously is limited. Operating the instrument at less than this limitation is referred to as derating. Do not measure currents in excess of the derating curve. Damage to the instrument or overheating can malfunction, a fire, or burn.

### Affix around the wire and check the measured value.


#### Leakage current measurement

Single-phase 3-wire circuit




- For measurement of grounded wires, clamp the instrument on one wire only (see a in the figure).
- For overall measurement, clamp the instrument on the entire circuit's wires bundled together (see b in the figure).
- To measure a single-phase 2-wire circuit, clamp both of the circuit's wires together.
- To measure a 3-phase 4-wire circuit, clamp all 4 of the circuit's wires bundled together. If this is not possible, carry out the measurement on the equipment's ground wire.
- Measurement may not be accurate in the cases below. (1) If there is large current flowing through a nearby electric line. (2) If you use the instrument to measure the waveforms on the secondary side of an inverter, or other special waveforms.
- Note that a large display count may appear momentarily when opening or closing the jaws. This is not an error. It may take some time for the display to return to zero. However, starting measurement before the display returns to zero will not affect measurement.

3-phase 3-wire circuit



#### AC current measurement, frequency measurement



- Clamp the instrument on one wire only.
- Put the conductor perpendicular to the sensor.
- Correct measurement may be impossible for the case of rush current or significantly fluctuating current.
- At a low temperature, there are cases when the reading may not be around zero without any input signal. But it does not affect measurement.
- Press **RANGE** key for 1 sec. or more to switch frequency measurement and current measurement.

#### Over-input warning (Red backlight or flashing red backlight + beep)




The measured value is beyond the measurable range of current measurement. Halt measurement as the instrument is in an over-input state. The backlight will also turn red if the comparator or event function threshold is exceeded.

## Useful Functionality

### Auto hold function


When the measured value stabilizes, the value automatically retains.



### Comparator function

If the present threshold value is exceeded, the instrument will sound an intermittent beep, and the display will turn red.

### Changing the threshold values




### Filter function

The effects of noise can be reduced by the low-pass filter.

The passband is -3 dB at 180 Hz ±30 Hz. Turn off the filter function when performing measurement of current frequencies in excess of 180 Hz. When the filter function is enabled, the indicated value may be lower than the actual value.

### AC Inrush function (Inrush current measurement)

The measured value (RMS value) is retained when an inrush current is detected.



Repeat measurement by pressing the **HOLD** key. Revert to normal measurement by pressing and holding the **MAX/MIN** key and **RANGE** key at the same time for 1 sec. or more. The inrush range is fixed at the range during current measurement. Specifically, the inrush range is fixed to the 600.0 A range when using the auto range for current measurement and to the 60.0 mA range for current measurement.

### Auto power save (APS) function

The instrument will turn off if there is no input and no operation for about 10 min.

## Repairs, Inspections, and Cleaning

If the instrument seems to be malfunctioning, confirm that the battery is not discharged before contacting your authorized Hioki distributor or reseller.

During shipment of the instrument, handle it carefully so that it is not damaged due to a vibration or shock.

### Cleaning

If the instrument becomes dirty, wipe the instrument clean with a soft cloth slightly moistened with water or a neutral detergent.

### Error display

When an error is displayed on the LCD screen, repair is necessary. Please contact your authorized Hioki distributor or reseller.


- [Err 1]** ROM error (program)
- [Err 2]** ROM error (adjustment data)
- [Err 4]** Memory error
- [Err 8]** Z3210 communication error (bad connection, malfunction of Z3210 or hardware)

### Wireless function (GENNECT Cross)

When the wireless function is enabled, you can review measurement data and create measurement reports on mobile devices. For more information about this functionality, see the [Help](#) function in the GENNECT Cross (application software, free of charge).


#### 1 Connect the Z3210 Wireless Adapter (option) to the instrument.

1. Turn off the power switch and disconnect the clamp from the object under measurement.
2. Remove the battery cover by turning screws.
3. Remove the protective cap.
4. Exercising care to orient the Z3210 correctly, insert the Z3210 as far as it will go.



#### 2 Install the GENNECT Cross on your mobile device.

#### 3 Turn on the power switch and confirm that the wireless function is enabled.



#### 4 Launch the GENNECT Cross and pair it with the instrument.

#### 5 Select the measurement function (such as General Measurement and Waveform Graph function) and start measurement.

- The communication distance is approx. 10 m (line of sight). The distance over which data can be sent and received varies greatly depending on whether there are any obstructions between the paired instruments (for example, walls, metal barriers, etc.) and on the distance between the instrument and the floor (or ground). To ensure stable measurement, verify adequate signal strength.

- Although this application software is provided free of charge, downloading or using the application software may incur internet connection charges. Such charges are the sole responsibility of the user.
- This application software is not guaranteed to operate on all mobile devices.

### Event function

- By using GENNECT Cross, you can set a threshold value as desired and record data if it is exceeded. The instrument displays the number of events recorded. For more information, see the [Help](#) function in the GENNECT Cross.


### Replace battery



**WARNING**

To avoid electric shock, turn off the power switch and disconnect the clamp from the object under measurement before replacing the battery.

	Fully charged.
	As the battery charge diminishes, black charge bars disappear, one by one, from the left of the battery indicator.
	The battery voltage is low. Replace the battery as soon as possible.
	(Flashes) The battery is exhausted. Replace the battery.



- 1 Remove the battery cover by turning screws.
- 2 Replace the battery.
- 3 Replace the battery cover and secure in place with the screw.